# Rotor Assembly 5




Figure 1

## Base Substrate 30




Figure 2




Figure 3

### Interconnects 50




Figure 4

## Stator Coils 35




Figure 5

## Magnetic Flux Return 38




Figure 6

### Stator Assembly 70




Figure 7

# Motor Assembly 100




Figure 8




Figure 9

- Magnetization 0-60 degrees 120-180 degrees 240-300 degrees

Magnetization
60-120 degrees
180-240 degrees
300-360 degrees

1 Inward Leg 0-20 degrees 2 Outward Leg




Figure 10

